

Mr G O Milne

April 26th, 1941

Wilfred S Roberts

In a number of recent instances, the announcers' log has shown that chimes came up late, and the shows of course were debited with runovers. In checking with my producers on the shows in question, their stories have been that the chime button was pushed at the proper time or a second or two later than the proper time, but that chimes did not actually come up until in some cases ten seconds beyond that point. Can this have any basis in fact?

I am not referring to synchronisation - of course it is necessary for both networks to get together before chimes will ring - but what I am curious to know from you is whether there is any possible mechanical or electrical error that could account for this situation.

Wilfred S Roberts

WER:AE