

Tested extra sparkers
on 11th floor RCA Bldg.
Beta not sufficient
to pilot coil as compared
with increasing frequency of
climbs from 1 hour to $\frac{1}{2}$ hour
basis - also adding home
strike mechanism.

Former being done (if reqs. are
approved by CDM) - latter
awaits delivery of mechanism
from RCA.

4/5/39
J